

P BURILES EN CARBURO

LOM1401

Borde plano



Ref.	L = mm	A = mm
LOM1401-2-C	45	0,2
LOM1401-4-C	45	0,4
LOM1401-6-C	45	0,6
LOM1401-8-C	45	0,8
LOM1401-10-C	45	1,0
LOM1401-12-C	45	1,2
LOM1401-14-C	45	1,4

LOM1402

Borde redondo



Ref.	L = mm	A = mm
LOM1402-2-C	45	0,2
LOM1402-4-C	45	0,4
LOM1402-6-C	45	0,6
LOM1402-8-C	45	0,8
LOM1402-10-C	45	1,0

LOM1403

De punta



Ref.	L = mm	A = mm
LOM1403-0-C	45	1,40
LOM1403-1-C	45	1,55
LOM1403-2-C	45	1,65
LOM1403-3-C	45	1,75
LOM1403-4-C	45	2,0

LOM1406

De cuchillo



Ref.	L = mm	$\alpha = ^\circ$
LOM1406-30-C	45	30
LOM1406-45-C	45	45
LOM1406-60-C	45	60
LOM1406-75-C	45	75
LOM1406-90-C	45	90
LOM1406-105-C	45	105

LOM0401

Borde plano



Ref.	L = mm	A = mm
LOM0401-2-HSS	55	0,2
LOM0401-4-HSS	55	0,4
LOM0401-6-HSS	55	0,6
LOM0401-8-HSS	55	0,8
LOM0401-10-HSS	55	1,0
LOM0401-12-HSS	55	1,2
LOM0401-14-HSS	55	1,4

LOM0402

Borde redondo



Ref.	L = mm	A = mm
LOM0402-2-HSS	55	0,2
LOM0402-4-HSS	55	0,4
LOM0402-6-HSS	55	0,6
LOM0402-8-HSS	55	0,8
LOM0402-10-HSS	55	1,0

LOM0403

De punta



Ref.	L = mm	A = mm
LOM0403-5/0-HSS	55	1,16
LOM0403-4/0-HSS	55	1,24
LOM0403-3/0-HSS	55	1,35
LOM0403-2/0-HSS	55	1,45
LOM0403-0-HSS	55	1,58
LOM0403-1-HSS	55	1,78
LOM0403-2-HSS	55	1,94
LOM0403-3-HSS	55	2,16
LOM0403-4-HSS	55	2,54

LOM0406

De cuchillo



Ref.	L = mm	A = mm
LOM0406-18-HSS	55	1,8
LOM0406-20-HSS	55	2,0
LOM0406-22-HSS	55	2,2

Adaptado para mandril \varnothing 3,2 mm/1/8"